

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-022	Smoke	8/12/2008	ADS/TM	S09UU_009MH	Dry	Yes	1,870.62



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-022	Smoke	8/12/2008	ADS/TM	S09UU_009MH	Dry	Yes	1,870.62

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S07WW_005G1	S07WW_005MH	S09WW_003MH	308.9645	8
S09UU_014G1	S09UU_014MH	S09UU_002MH	252.5525	8
S09UU_011G1	S09UU_011MH	S09UU_001MH	391.6530	12
S09UU_009G1	S09UU_009MH	S09UU_014MH	357.7176	8
S09UU_002G1	S09UU_002MH	S09UU_011MH	345.6679	8
S09WW_003G1	S09WW_003MH	S09UU_009MH	214.0658	8

Observations & Photos

Obs_ID S1028-022-OB01

Address 3309 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_002MH

Comments Smoke from cleanout in front yard. 3309 W. Forest Park Ave.



Picture \S1028-022-OB01-P01.jpg

Comments Front of house, 3309 W. Forest Park Ave.

Obs_ID S1028-022-OB02

Address 3317 W. Forest Park Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_002MH

Comments Smoke from cleanout in front yard. 3317 W. Forest Park Ave.



Picture \S1028-022-OB02-P01.jpg

Comments Front of house, 3317 W. Forest Park Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-022	Smoke	8/12/2008	ADS/TM	S09UU_009MH	Dry	Yes	1,870.62

Obs_ID S1028-022-OB03

Address 3300 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_002MH

Comments Smoke from cleanout in front yard. 3300 W. Forest Park Ave.



Picture \S1028-022-OB03-P01.jpg

Comments Front of house, 3300 W. Forest Park Ave.

Obs_ID S1028-022-OB05

Address 3325 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_002MH

Comments Smoke from cleanout in front yard. 3325 W. Forest Park Ave.



Picture \S1028-022-OB05-P01.jpg

Comments Front of house, 3325 W. Forest Park Ave.

Obs_ID S1028-022-OB04

Address 3310 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_002MH

Comments Smoke from cleanout in front yard. 3310 W. Forest Park Ave.



Picture \S1028-022-OB04-P01.jpg

Comments Front of house, 3310 W. Forest Park Ave.

Obs_ID S1028-022-OB06

Address 3316 Denison St

Status Private

Source Cleanout

Location Yard - side

Nearest MH S09UU_002MH

Comments Smoke from cleanout in Side yard. 3316 Denison St.



Picture \S1028-022-OB06-P01.jpg

Comments Side of house, 3316 Denison St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-022	Smoke	8/12/2008	ADS/TM	S09UU_009MH	Dry	Yes	1,870.62

Obs_ID S1028-022-OB07

Address 3406 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_014MH

Comments Smoke from cleanout in front yard. 3406 W. Forest Park Ave.



Picture \S1028-022-OB07-P01.jpg

Comments Front of house, 3406 W. Forest Park Ave.

Obs_ID S1028-022-OB08

Address 3408 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_014MH

Comments Smoke from cleanout in front yard. 3408 W. Forest Park Ave.



Picture \S1028-022-OB08-P01.jpg

Comments Front of house, 3408 W. Forest Park Ave.

Obs_ID S1028-022-OB09

Address 3412 W. Forest Park Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_009MH

Comments Smoke from cleanout in front yard. 3412 W. Forest Park Ave.



Picture \S1028-022-OB09-P01.jpg

Comments Front of house, 3412 W. Forest Park Ave.

Obs_ID S1028-022-OB10

Address 3414 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_009MH

Comments Smoke from cleanout in front yard. 3414 W. Forest Park Ave.



Picture \S1028-022-OB10-P01.jpg

Comments Front of house, 3414 W. Forest Park Ave.



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-022	Smoke	8/12/2008	ADS/TM	S09UU_009MH	Dry	Yes	1,870.62

Obs_ID S1028-022-OB11

Address 3415 W. Forest Park Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S09UU_009MH

Comments Smoke from cleanout in front yard. 3415 W. Forest Park Ave.



Picture \S1028-022-OB11-P01.jpg

Comments Front of house, 3415 W. Forest Park Ave.

Obs_ID S1028-022-OB12

Address 3500 W. Forest Park Ave

Status Private

Source Cleanout

Location Yard - side

Nearest MH S09UU_009MH

Comments Smoke from cleanout in Side yard of house. 3500 W. Forest Park Ave.



Picture \S1028-022-OB12-P01.jpg

Comments Front of house, 3500 W. Forest Park Ave.
